

Pneumatic Fastener Gun Safety and Operation

NOTICE Rules and guidelines listed on this page are only reminders. Persons must read lab safety manual, machine manual, and be trained by WRL Manager.



Safety Rules

- Safety glasses are required.
- Assume tool always contains fasteners.
- Don't wear loose clothing or gloves, keep long hair tied back.
- Keep bystanders away when using a pneumatic fastener gun.
- Keep fingers 2-3" away from working point.
- Never remove guard.
- Never point the tool at anyone including yourself.
- Never depress trigger unless nose is against material in a safe manner.
- Load with air disconnected and finger off the trigger.
- Take special care when working near the edge of material or at a skew.
- If machine is malfunctioning stop immediately and report to supervisor.